

In-Production Photo Report for

Enforcer Aerial

Haverhill Fire Department, MA

Job# 41804

Status as of October 16, 2026

In this report your cab completed initial assembly, the frame build continued, the transverse was painted and staged, the torque box arrived and was staged, and the body continued through paint. In the next report your cab may be staged, the frame build may continue, the transverse and the torque box may be staged, and the body may continue the paint process.





DSC01066



DSC01067



DSC01068



DSC01069




DSC01070



DSC01071



DSC01072



DSC01039



DSC01040



DSC01041



DSC01042



DSC01043



DSC01044



DSC01045



DSC01046



DSC01047



DSC01048



DSC04264



DSC04265



DSC04266




DSC04052



DSC04053



DSC04054



DSC02530



DSC02531



DSC02532



DSC02533



DSC02534



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company