

In-Production Photo Report for

Velocity Pumper


Londonderry Fire Department, NH

Job# 42152

Status as of August 28, 2026

In this report your cab and pump house were merged with the frame while the body completed paint. In the next report your chassis may be staged to continue assembly while the body may continue begin initial assembly.





DSC03255



DSC03256



DSC03257



DSC03258




DSC03259



DSC03260



DSC03261



DSC03262



DSC03263



DSC03264



DSC03265



DSC05138



DSC05139



DSC05140



DSC05141



DSC05142



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company