

In-Production Photo Report for

Velocity Pumper

Londonderry Fire Department, NH

Job# 42152

Status as of September 03, 2026

In this report your chassis was staged to continue assembly while the body began initial assembly. In the next report the body may complete initial assembly and be merged with the chassis at the start of initial apparatus assembly.






DSC01255



DSC01256




DSC01257




DSC01258



DSC01259



DSC01260




DSC01261



DSC01262



DSC01263



DSC02504



DSC02505



DSC02506



DSC02507



DSC02508



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company