

In-Production Photo Report for

Enforcer Pumper

Hudson Fire Department, MA

Job# 42355

Status as of October 16, 2026

In this report your cab and pump were merged with the frame while the body began initial assembly. In the next report your chassis may remain staged to continue assembly while the body may continue initial assembly.






DSC01431



DSC01432



DSC01433



DSC01434



DSC01435



DSC01436




DSC01437



DSC01438



DSC01439



DSC01478



DSC01479



DSC01480



DSC01481



DSC01482



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company