

In-Production Photo Report for

Enforcer Pumper


Hudson Fire Department, MA

Job# 42355

Status as of September 25, 2026

In this report your cab began initial assembly, the frame build began, the pump house was staged to continue initial assembly, and the body began the paint process with metal finishing. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue through paint.






DSC01158



DSC01159



DSC01160



DSC01161



DSC01162




DSC01212




DSC01213



DSC01214



DSC01215



DSC01216



DSC01217



DSC01218



DSC01219



DSC01220



DSC01221



DSC04044




DSC04045




DSC04046



DSC04047



DSC04048



DSC04670



DSC04671



DSC04672



DSC04673



DSC04674



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company