Photo Album for Carver, MA Job # 34635 W/O # 26013087 September 26, 2020

This week the pump house structure began fabrication and the fire pump continued to receive valves and plumbing. The body began fabrication. Next week the chassis may arrive, and the pump house structure should finish fabrication. The fire pump should continue to receive valves and plumbing, and the body should continue with fabrication.



DSC00177



DSC00179



DSC00178



DSC00180





DSC00181



DSC00183



DSC00182



DSC00184





DSC00185



DSC00187



DSC00186

