Photo Album for Shirley Fire Department, MA Job 38170 April 14, 2023

In this report your cab made progress through paint and was staged, your pump house continued initial assembly, and your body was fabricated and began the paint process. In the next report your cab may remain staged to begin initial assembly, the pump house may continue initial assembly, and the body may continue through paint.



DSC04711



DSC04713



DSC04712



DSC04714





DSC04715



DSC07063



DSC07062



DSC07064





DSC07065



DSC04776



DSC07066



DSC04777





DSC04778



DSC04780



DSC04779

