



Photo Album for Shirley Fire Department, MA Job 38170 April 28, 2023

In this report your cab started initial assembly, the frame build began, your pump house remained staged, and your body continued through paint. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may remain staged, and the body may continue the paint process.



DSC05080



DSC05081



DSC05082



DSC05083



DSC05084



DSC01000



DSC01001



DSC01002



DSC01003



DSC01004



DSC01076



DSC01077



DSC01078



DSC01079



DSC01080



DSC04618



DSC04619



DSC04620



DSC04621