Photo Album for Springfield Fire Department, MA Job 37454 April 14, 2023

In this report your cab began initial assembly, the frame build began, and the body continued through paint. In the next report your cab may continue initial assembly, the frame build may continue, and the body may continue the paint process.



DSC04930



DSC04932



DSC04931



DSC04933





DSC04934



DSC01001



DSC01000




DSC01002





DSC01003




DSC04644



DSC01004



DSC04645







DSC04646



DSC04648



DSC04647

