Photo Album for West Springfield Fire Department, MA Job 38084 May 05, 2023

In this report the torque box was installed on the chassis while the body began initial assembly. In the next report your chassis may remain staged while the body may continue initial assembly.







DSC04787



© 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956









DSC04791





DSC04793 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC04795





DSC04797 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956







DSC04799





© 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956










DSC04802





DSC01302

DSC01304 © 2005 - 2023 Fire & Safety Consulting, LLC Neenah, Wisconsin 54956





