

Photo Album for West Springfield Fire Department, MA Job 38084 May 12, 2023

In this report the body completed initial assembly and was merged with the chassis, followed by the start of final assembly. In the next report your apparatus may continue final assembly.



DSC01262



DSC01263




DSC01264




DSC01265



DSC01266



DSC01267



DSC01268



DSC01269



DSC01270



DSC01271



DSC01272



DSC01273



DSC01274



DSC01275



DSC01276



DSC01277



DSC01278



DSC01279



DSC01280



DSC01281



DSC01282



DSC01283



DSC01284



DSC01285



DSC01286



DSC01287



DSC01288



DSC01289



DSC01290



DSC01291



DSC01292



DSC01293




DSC01294



DSC01295



DSC01296



DSC01297



DSC01298



DSC01299



DSC01300



DSC01301



DSC01302



DSC01303



DSC01304



DSC01305



DSC01306