
In-Production Photo Report for Hudson Fire Department, MA Job# 39376 Status as of January 19, 2024

> In this report the cab continued through paint, the pump house structure was fabricated, and the body began fabrication. In the next report your cab may continue the paint process, the pump house structure may remain staged, and the body may continue fabrication.

> > For Valued Customers of







DSC00725



DSC00726



DSC00727



DSC00038

DSC00013







DSC00039





DSC00012





DSC00016

DSC00015





https://allegiancefr.com



An Oshkosh Corporation Company