In-Production Photo Report for Hudson Fire Department, MA Job# 39376 Status as of February 07, 2024

> In this report the cab continued initial assembly, the pump house continued initial assembly, and the body began the paint process. In the next report the cab and pump house may continue initial assembly while the body may continue the paint process.

> > For Valued Customers of








DSC00013



DSC00015



DSC00014



DSC03011

DSC03014



DSC03012





DSC03013



DSC00782



DSC00780



DSC00781





https://allegiancefr.com

ALLEGIANCE _____TRUCKS*____



An Oshkosh Corporation Company