

In-Production Photo Report for South Portland Fire Department, ME Job# 38003

Status as of February 16, 2024


In this report your cab completed initial assembly, the frame build continued, the pump house structure was staged, the torque box continued initial assembly, the front body module was unavailable for photos, and the rear body module completed paint. In the next report the cab may remain staged, the frame build may continue, the pump house may begin initial assembly, the torque box may continue initial assembly, the front body module may be available, and rear body module may begin initial assembly.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00212



DSC00213



DSC00214




DSC00301



DSC00302



DSC00303



DSC00304



DSC00305



DSC00306



DSC00307



DSC00308



DSC00052



DSC00053



DSC00054



DSC00055



DSC00084



DSC00085



DSC00086



DSC00087



DSC00088



DSC00956



DSC00957



DSC00958



DSC00959



DSC00960



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S —



An Oshkosh Corporation Company