In-Production Photo Report for Brockton Fire Department, MA Job# 38748 Status as of March 15, 2024

> In this report your cab completed initial assembly, the torque box was staged, and the body began the paint process. In the next report the cab and torque box may remain staged while the body may continue through paint.












DSC00070










DSC00062



DSC00063





DSC00692











https://allegiancefr.com



An Oshkosh Corporation Company