


In-Production Photo Report for Brockton Fire Department, MA Job# 38748


Status as of April 05, 2024

In this report the torque box and body were merged with the chassis followed by the start of final assembly.
In the next report final assembly may continue.



For Valued Customers of





DSC03201



DSC03202



DSC03203



DSC03204



DSC03205



DSC03206



DSC03207



DSC03208



DSC03209



DSC03210



DSC03211



DSC03212



DSC03213



DSC03214



DSC03215



DSC03216



DSC03217



DSC03218



DSC03219



DSC03220



DSC03221



DSC03222



DSC03223



DSC03224



DSC03225




DSC03226




DSC03227



DSC03228



DSC03229



DSC03230



DSC03231



DSC03232



DSC03233



DSC03234



DSC03235



DSC03236



DSC03237



DSC03238



DSC03239



DSC03240



DSC03241



DSC03242



DSC03243



DSC03244



DSC03245



DSC03246



DSC03247



DSC03248



DSC03249




DSC03250



DSC03251



DSC03252



DSC03253



DSC03254



DSC03255



DSC03256



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S —



An Oshkosh Corporation Company