

In-Production Photo Report for Plaistow Fire Department, NH Job# 38805

Status as of April 05, 2024


In this report the cab continued initial assembly, the frame build began, the pump house began initial assembly, the torque box was staged, the front body module began the paint process, and the rear body module remained staged. In the next report your cab may remain staged, the frame build may continue, the pump house may continue initial assembly, the torque box may remain staged, the front body module may continue through paint, and the rear body module may begin the paint process.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00165



DSC00166




DSC00167




DSC00329



DSC00330



DSC00331




DSC00332



DSC00333




DSC00334



DSC00335



DSC00336



DSC00337



DSC00120



DSC00121




DSC00122



DSC00123



DSC00124



DSC00130



DSC00131



DSC00132



DSC00133



DSC00134



DSC00365



DSC00366



DSC00367



DSC03003



DSC03004



DSC03005



DSC03006



DSC03007



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S[®] —



An Oshkosh Corporation Company