In-Production Photo Report for

Brockton Fire Department, MA Job# 38749

Status as of April 05, 2024

In this report the cab completed initial assembly, the frame build began, the transverse compartment completed paint, the torque box remained staged, the front body module completed paint, and the rear body module completed paint and was staged. In the next report the cab may remain staged, the frame build may continue, the transverse compartment may be staged, the torque box may begin initial assembly, the front body module may remain staged, and the rear body module may begin initial assembly.







DSC00150



DSC00152



DSC00151




DSC00153



DSC00154



DSC00203




DSC00202




DSC00204



DSC00205



DSC00207



DSC00206



DSC00208




DSC00942



DSC00944



DSC00943



DSC00140



DSC00141



DSC00143



DSC00142



DSC00144



DSC00541



DSC00543



DSC00542



DSC00452



DSC00453



DSC00455



DSC00454



DSC00456





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company