

In-Production Photo Report for Merrimack Fire Department, NH Job# 38808

Status as of April 12, 2024

In this report your cab began initial assembly, the pump house structure was fabricated and staged, the torque box was staged, the front body module completed paint, and the rear body module completed fabrication. In the next report your cab may continue initial assembly, the pump house structure may be painted, the torque box may remain staged, the front body module may remain staged, and the rear body module may remain staged to begin the paint process.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00401



DSC00402



DSC00403



DSC00404



DSC00405



DSC00083



DSC00084



DSC00085



DSC00086



DSC00087



DSC00156



DSC00157



DSC00158



DSC00159



DSC00160



DSC03278



DSC03279



DSC03226



DSC03227



DSC03228



DSC03229



DSC03230



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S —



An Oshkosh Corporation Company