

# In-Production Photo Report for Merrimack Fire Department, NH Job# 38808

---

Status as of May 03, 2024

In this report your cab remained staged, the frame build began, the pump house and torque box remained staged, the front body module completed initial assembly, and the rear body module completed paint. In the next report your cab, pump house, torque box, and front body module may remain staged, and the rear body module began initial assembly.



*For Valued Customers of*



POWERED BY  
**ALLEGIANCE**  
TRUCKS®



DSC03379



DSC03380



DSC03381



DSC03382



DSC03383



DSC03384



DSC03385



DSC03476



DSC03477



DSC03478



DSC03534



DSC03535



DSC03536



DSC03059



DSC03060



DSC03061



DSC03062



DSC03063



DSC00866



DSC00867



DSC00868



DSC00567



DSC00568



DSC00569



DSC00570



DSC00571





<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— T R U C K S<sup>®</sup> —



An Oshkosh Corporation Company