**In-Production Photo Report for** Brockton Fire Department, MA Job# 38747 Status as of May 10, 2024

In this report your cab completed fabrication and began the paint process, the transverse compartment was fabricated, the pump house structure remained staged, and the body was fabricated and staged. In the next report your cab may continue through paint, the transverse compartment may be painted, the pump house structure may remain staged, and the body may remain staged to begin the paint process.

For Valued Customers of





DSC01483








DSC01481







DSC01485




DSC03538






DSC03541

## DSC03450







DSC00345







<image>

DSC03453





https://allegiancefr.com

## ALLEGIANCE \_\_\_\_\_TRUCKS\*\_\_\_\_



An Oshkosh Corporation Company