

In-Production Photo Report for Auburn Fire Department, ME Job# 38828

Status as of July 12, 2024

In this report your cab began initial assembly, the frame build continued, the pump house was painted then began initial assembly, the torque box arrived and was staged, and the body completed fabrication. In the next report your cab may continue initial assembly, the frame build may continue, the pump house may continue initial assembly, the torque box may remain staged, and the body may remain staged to begin the paint process.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00246



DSC00247



DSC00248



DSC00249




DSC00250



DSC00354



DSC00355



DSC00356



DSC00357



DSC00358



DSC00359



DSC00360



DSC00361



DSC00362



DSC00363



DSC00364



DSC03078



DSC03079



DSC03080



DSC03081



DSC03082



DSC03000



DSC03001



DSC03002



DSC03003



DSC03004



DSC03096



DSC03097



DSC03098



DSC03099



DSC03100



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— TRUCKS® —



An Oshkosh Corporation Company