

In-Production Photo Report for Auburn Fire Department, ME Job# 38828

Status as of July 19, 2024


In this report both your cab and the pump house completed initial assembly and were installed on the frame, the torque box remained staged, and the body began the paint process. In the next report your chassis may remain staged to continue assembly while the torque box may begin initial assembly, and the body may continue through paint.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC03069



DSC03070



DSC03071



DSC03072



DSC03073



DSC03074



DSC03075



DSC03076




DSC03077



DSC03078



DSC03079



DSC03080



DSC03081



DSC03082



DSC03083



DSC03084



DSC03085



DSC03086



DSC03087



DSC03088



DSC03089



DSC03090



DSC03091



DSC03092



DSC03093



DSC03094



DSC03095



DSC03096



DSC03097



DSC03098



DSC03099



DSC03100



DSC03101



DSC03102



DSC03103



DSC03104



DSC03105



DSC03106




DSC03107



DSC03108



DSC03109



DSC03110



DSC03111



DSC03112



DSC03113



DSC03114



DSC03115



DSC03116




DSC03117



DSC03118



DSC03119



DSC03120



DSC03121




DSC03122



DSC03123



DSC03124



DSC03125



DSC03126



DSC03127



DSC03128



DSC03129



DSC03130



DSC03131



DSC03132



DSC03133



DSC03134



DSC03135



DSC03136



DSC03137



DSC03138



DSC03139



DSC03140



DSC03141



DSC03142



DSC03143



DSC03144



DSC03145



DSC03146



DSC00475



DSC00476



DSC00477



DSC00478



DSC00479



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— TRUCKS® —



An Oshkosh Corporation Company