
In-Production Photo Report for New Bedford Fire Department, MA Job# 38803 Status as of August 02, 2024

> In this report your apparatus completed final assembly while the aerial device completed initial assembly and was pinned to the apparatus followed by the start of aerial testing. In the next report testing may continue.





anufactu	anufacturi red Exclusively f EDFORD	ng, Inc. For -	TH EPA YE/ V	VEHICLE CONTROL IN Vehicle Family: F Sub-Category: Er IS VEHICLE CON REGULATIONS AR HEAVY-DUTY EHICLE WAS CE RGENCY VEHIC 1037.10	FORM MPLIES FOR 21 VEHIC RTIFIE LE UNE
4	Job No.	38803		WO No.	309
B) Tire-Lir Max Sj		68	mph	Chassis	Ente
TIRES		RIMS		COLD TIRE IN	FLAT
B) 315	/80R22.5 (L) 5/80R22.5 (L) 5/65R22.5 (L)	22.50x9.00 22.50x9.00 22.50x12.25	861 827 827	kPa (125 PS kPa (120 PS kPa (120 PS	4) S 4) C 4) S



<image>

DSC00913



DSC00915





DSC00917



DSC00919





DSC00921



DSC00923







DSC00924







https://allegiancefr.com

ALLEGIANCE _____TRUCKS*____



An Oshkosh Corporation Company