

In-Production Photo Report for Bellingham Fire Department, MA Job# 42579

Status as of January 17, 2025

In this report the torque box completed initial assembly and was merged with the chassis followed by the body completing initial assembly and then installed at the start of initial apparatus assembly. In the next report your apparatus may complete initial assembly and begin final assembly.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®




DSC00376



DSC00377



DSC00378



DSC00379




DSC00380



DSC00381



DSC00382



DSC00383



DSC00384



DSC00385



DSC00386



DSC00387



DSC00388



DSC00389



DSC00390



DSC00391



DSC00392



DSC00393



DSC00394



DSC00395



DSC00396



DSC00397



DSC00398




DSC00399



DSC00400



DSC00401



DSC00402



DSC00403



DSC00404



DSC00405



DSC00406



DSC00407



DSC00408




DSC00409



DSC00410



DSC00411



DSC00412



DSC00413



DSC00414



DSC00415



DSC00416



DSC00417



DSC00418



DSC00419



DSC00420



DSC00421



DSC00422



DSC00423



DSC00424



DSC00425



DSC00426



DSC00427



DSC00428



DSC00429




DSC00430



DSC00431



DSC00432



DSC00433



DSC00434



DSC00435




DSC00436



DSC00437



DSC00438



DSC03755




DSC03756



DSC03757



DSC03758



DSC03759



DSC03760



DSC03761



DSC03762



DSC03763



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— TRUCKS® —



An Oshkosh Corporation Company