

In-Production Photo Report for

Enforcer Pumper


Berlin Fire Department, NH

Job# 40661

Status as of August 28, 2026

In this report your cab completed initial assembly, the frame build continued, the pump house completed initial assembly, and the body was staged to continue through paint. In the next report your cab may be staged, the frame build may continue, the pump house may remain staged, and the body may continue the paint process.





DSC01056




DSC01057



DSC01058



DSC01059



DSC01060



DSC01061



DSC01062



DSC01142



DSC01143



DSC01144



DSC01145



DSC01146



DSC01147



DSC01148



DSC01149



DSC01150



DSC01151



DSC01152



DSC01153



DSC01154



DSC04019



DSC04020



DSC04021



DSC04022



DSC04237



DSC04238



DSC04239



DSC04240



DSC04241



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company