

In-Production Photo Report for

Enforcer Pumper


Berlin Fire Department, NH

Job# 40661

Status as of September 03, 2026

In this report your cab was staged, the frame build continued, the pump house remained staged, and the body continued the paint process. In the next report your cab and pump house may be staged, the frame build may continue, and the body may complete the paint process.





DSC01043



DSC01044



DSC01045



DSC01046



DSC01047



DSC01048




DSC01049



DSC01050



DSC01051



DSC01189



DSC01190



DSC01191



DSC01192



DSC01193



DSC01194



DSC01195



DSC01196



DSC01197



DSC01198



DSC04019



DSC04020



DSC04021



DSC04022



DSC04023



DSC02013



DSC02014



DSC02015



DSC02016



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company