

In-Production Photo Report for

Velocity Pumper


Londonderry Fire Department, NH

Job# 42152

Status as of October 16, 2026

In this report your apparatus completed testing followed by release to quality and graphics where any remaining content will be applied. In the next report testing may be complete and your apparatus may your apparatus may continue the quality process.





DSC01580



DSC01581



DSC01582



DSC01583



DSC01584



DSC01585



DSC01586



DSC01587



DSC01588



DSC01589




DSC01590



DSC01591



DSC01592



DSC01593



ALLEGIANCETM

FIRE & RESCUE



<https://allegiancefr.com>



An Oshkosh Corporation Company