

Photo Album for Carver, MA


Job # 34635

W/O # 26013087

October 10, 2020

Since the last report, the pump house structure was joined with the fire pump and began the paint process.

The body finished with fabrication. Next week the chassis should arrive, and the pump house should finish with paint. The body should begin the paint process.



DSC00688



DSC00689



DSC00690



DSC00691



DSC00692



DSC00693



DSC00694



DSC00695



DSC00696



DSC00697