



Photo Album for Peru Fire Department, VT

Job # 34978

W/O # 26236168

March 6, 2021

This week the chassis remained in staging (no photos) and the pump house structure was joined with the fire pump. The body remained in staging (no photos). Next week the chassis could begin preparations for fire service and the pump house could begin the paint process along with the body.



DSC00001



DSC00002



DSC00003



DSC00004