



Photo Album for  
Providence FD., RI  
Job # 35597-03  
W/O # 26981613  
March 6, 2021

This week the cab continued the paint process, and the chassis frame was in staging (no photos). The pump house structure was joined with the fire pump and began the paint process. The body was unavailable for photos in paint. Next week the cab should finish with paint and the chassis frame should be in staging. The pump house and body should finish with paint.



DSC00371



DSC00372



DSC00373



DSC00376





DSC00377