



Photo Album for Merrimack FD., NH

Job # 35860-02

W/O # 27181441

April 24, 2021

This week the cab finished with fabrication and the pump house structure along with the fire pump remained in staging (no photos). The body continued with fabrication. Next week the cab could begin the paint process and the chassis frame could arrive. The pump house structure could be joined with the fire pump and the body should finish with fabrication.



DSC00511



DSC00512



DSC00513



DSC00514



DSC00515



DSC00516



DSC00517



DSC00518