


# Photo Album for Sheffield Fire Department, MA Job 35583 April 23, 2021

In this report your cab made progress in paint while the body completed fabrication with release to paint. In your next report your cab may continue in paint while the body may begin the paint process.



DSC04715



DSC04716



DSC04717



DSC04718





DSC04719



DSC04942



DSC04943



DSC04944



DSC04945



DSC04946