




# Photo Album for Winslow Fire Department, ME Job 34817 August 07, 2020

This week your cab continued the content installation process, your chassis continued to have powertrain components installed, your torque box was prepared for installation, and your body components continued the paint process. Next week both your cab and PUC pump may be installed on your chassis while your body continues the paint process.



DSC07022



DSC07023



DSC07024



DSC07025





DSC07026



DSC06865



DSC06866



DSC06867





DSC06868



DSC06869




DSC06870



DSC06871



DSC06872



DSC00778



DSC00779



DSC00780





DSC00781



DSC00782



DSC01815



DSC01816





DSC01817



DSC01818



DSC01819



DSC01460



DSC01461



DSC01462



DSC01463



DSC01464