



Photo Album for Northampton Fire Department, MA Job 37773 May 05, 2023

In this report your cab completed fabrication and released to paint while the body began fabrication. In the next report your cab may begin the paint process while the body may continue fabrication.



DSC04543



DSC04544



DSC04545



DSC04546



DSC04547



DSC07124



DSC07125



DSC07126



DSC07127



DSC07128