



Photo Album for Salem Fire Department, MA Job 39351 May 26, 2023

In this report your cab remained staged, the transverse compartment began the paint process, and the body remained staged. In the next report your cab may begin initial assembly, the transverse compartment may continue through paint, and the body may begin the paint process.




DSC04781



DSC04782



DSC04783



DSC04784



DSC04785



DSC04692



DSC04693



DSC04694



DSC04876



DSC04877



DSC04878



DSC04879



DSC04880