



Photo Album for
Tewksbury Fire Dept., MA

Job # 37263

W/O # 30212170

May 27, 2023

This week the chassis was unavailable for photos and the body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body may finish with trim and wiring harnesses.



DSC00205



DSC00206



DSC00207



DSC00208