## Photo Album for Northampton Fire Department, MA Job 37773 June 23, 2023

In this report your cab continued initial assembly, the frame build continued, and the body completed the paint process and was staged. In the next report your cab may continue initial assembly, the frame build may continue, and the body may remain staged to begin initial assembly.



DSC04547



DSC04549



DSC04548



DSC04550





DSC04551



DSC04656



DSC04655



DSC04657





DSC04658



DSC04660



DSC04659



DSC05049





DSC05050



DSC05052



DSC05051



DSC05053

