

# In-Production Photo Report for Northampton Fire Department, MA Job# 37773

---


Status as of July 28, 2023

Since your last report the cab and torque box were installed on the frame, the body began initial assembly, and the aerial device arrived and was staged. In the next report the chassis may remain staged, the body may continue initial assembly, and the aerial device may remain staged.



POWERED BY  
**ALLEGIANCE**  
TRUCKS®

*For Valued Customers of*



DSC00064



DSC00065



DSC00066



DSC00067



DSC00068



DSC00069



DSC00070



DSC00071



DSC00072



DSC00073



DSC00074




DSC00075



DSC00076



DSC00077



DSC00841



DSC00842



DSC00843



DSC00844



DSC00845



DSC00846



DSC03034



DSC03035



DSC03036



DSC03037



DSC03038



DSC03039





<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— TRUCKS® —



An Oshkosh Corporation Company