

In-Production Photo Report for Marlborough Fire Department, MA Job# 39612


Status as of August 11, 2023

In this report the torque box and body were installed on the chassis followed by the start of final assembly while the aerial device remained staged (no photos).

In the next report the final assembly may continue while the aerial device may begin initial assembly.



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00582



DSC00583



DSC00584



DSC00585



DSC00586



DSC00587



DSC00588



DSC00589



DSC00590



DSC00591



DSC00592



DSC00593



DSC00594



DSC00595



DSC00597



DSC00598



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S —



An Oshkosh Corporation Company