## **In-Production Photo Report for**

Northampton Fire Department, MA Job# 37773

Status as of August 04, 2023

In this report the body was merged with the chassis followed by the start of final assembly, and the aerial device remained staged. In the next report the apparatus may continue final assembly, and the aerial device may begin initial assembly.

For Valued Customers of







DSC03142



DSC03144



DSC03143



DSC03145



DSC03146



DSC03148



DSC03147




DSC03149



DSC03150



DSC03152



DSC03151



DSC03153



DSC03154



DSC03156



DSC03155



DSC03157



DSC03158



DSC03160



DSC03159



DSC03161



DSC03162



DSC00180



DSC03163



DSC00181







DSC00183





https://allegiancefr.com





An Oshkosh Corporation Company