In-Production Photo Report for

Northampton Fire Department, MA Job# 37773

Status as of August 25, 2023

In this report your apparatus was staged while the aerial device continued assembly. In the next report the apparatus may complete final assembly and release to initial test while the aerial device may continue assembly.

For Valued Customers of









DSC00413



DSC00415



DSC00414



DSC00416



DSC00417



DSC00419



DSC00418



DSC00420



DSC00421



DSC00423



DSC00422



DSC00424



DSC00425



DSC00427



DSC00426




DSC00428



DSC00429



DSC00431



DSC00430




DSC00432



DSC00433



DSC03362



DSC03361



DSC03363





DSC03364 DSC03365





https://allegiancefr.com

ALLEGIANCE TRUCKS*



An Oshkosh Corporation Company