


In-Production Photo Report for Northampton Fire Department, MA Job# 37773

Status as of September 08, 2023


In this report the aerial device was pinned to the apparatus followed by the start of aerial testing. In the next report aerial testing may continue.



For Valued Customers of



POWERED BY
ALLEGIANCE
TRUCKS®



DSC00990



DSC00991



DSC00992



DSC00993



DSC00994



DSC00995



DSC00996



DSC00997



DSC00998



DSC00999



DSC01000



<https://allegiancefr.com>

POWERED BY
ALLEGIANCE
— T R U C K S —



An Oshkosh Corporation Company