## **In-Production Photo Report for**

Northampton Fire Department, MA Job# 37773

Status as of September 15, 2023

In this report aerial testing completed followed by release to quality and graphics where any remaining content will be applied. In the next your apparatus may continue through quality and graphics.


For Valued Customers of











DSC01718



DSC01720



DSC01719



DSC01721





DSC01722



DSC01723



DSC01724 DSC01725



DSC01726






DSC01727



DSC01728 DSC01729



DSC01730



DSC01732



DSC01731



DSC01733



DSC01734



DSC01736



DSC01735



DSC01737



DSC01738



DSC01740



DSC01739





https://allegiancefr.com

## ALLEGIANCE TRUCKS\*



An Oshkosh Corporation Company