

# In-Production Photo Report for Attleboro Fire Department, MA Job# 38049

---

Status as of September 22, 2023


In this report your cab completed the paint process, the frame build continued, the pump house continued initial assembly, and the body began the paint process. In the next report the cab may remain staged to begin initial assembly, the frame build may continue, the pump house may continue initial assembly, and the body may continue through paint.



*For Valued Customers of*



POWERED BY  
**ALLEGIANCE**  
TRUCKS®




DSC00208



DSC00209



DSC00210



DSC00217



DSC00218



DSC00219



DSC00097




DSC00098




DSC00099



DSC00100



DSC00101



DSC00811



DSC00812



DSC00813



DSC00814



DSC00815



<https://allegiancefr.com>

POWERED BY  
**ALLEGIANCE**  
— T R U C K S —



An Oshkosh Corporation Company