



Photo Album for
Belchertown Fire Dept., MA

Job # 38229

W/O # 30682673

August 26, 2023

This week the chassis was unavailable in paint and the fire pump began to receive valves and plumbing. Next week the chassis should finish with paint and the fire pump may be joined with the pump house structure.



DSC00206



DSC00207



DSC00208



DSC00209