



Photo Album for
Belchertown Fire Dept., MA

Job # 38229

W/O # 30682673

October 14, 2023

This week the chassis continued with chassis prep and the pump house was in staging. The body continued to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house should be mounted and may be the body.



DSC00219



DSC00220



DSC00221



DSC00222



DSC00223



DSC00224



DSC00225



DSC00226



DSC00227



DSC00228



DSC00229



DSC00230




DSC00231



DSC00232



DSC00279



DSC00280



DSC00281



DSC00282



DSC00283