



Photo Album for  
Belchertown Fire Dept., MA

Job # 38229

W/O # 30682673

October 21, 2023

This week the chassis continued with chassis prep and the pump house was mounted. The body continued to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the body should be mounted.





DSC00337



DSC00338



DSC00339



DSC00340





DSC00341



DSC00350



DSC00351



DSC00352



DSC00353