



Photo Album for
Belchertown Fire Dept., MA

Job # 38229

W/O # 30682673

October 28, 2023

This week the chassis continued with chassis prep and the body was in staging. Next week the chassis should continue with chassis prep and the body should be mounted.



DSC00244




DSC00245



DSC00246



DSC00247




DSC00248



DSC00249



DSC00250



DSC00251



DSC00252



DSC00253



DSC00254



DSC00255