



Photo Album for Belchertown Fire Dept., MA

Job # 38229

W/O # 30682673

October 7, 2023

This week the chassis continued with chassis prep and the pump house continued with final pump assembly. The body began to receive trim and wiring harnesses. Next week the chassis should continue with chassis prep and the pump house should be mounted. The body should finish with trim and wiring harnesses.



DSC00238



DSC00239



DSC00240



DSC00241



DSC00242



DSC00319



DSC00320



DSC00321



DSC00322



DSC00323



DSC00324



DSC00325



DSC00326



DSC00327



DSC00328



DSC00329



DSC00330